



Bermuda Keelboa Damage Report

Reported: 2024-10-06

Races: 5-8

Boat: IOD, Sail: 5, Bow: , Encore

Skipper: IOD - BER BERMUDA 1 - Craig Davis

Pre-Existing Damage: No Pre-existing Damage

Traveller is useless

Contact: No Contact

Damage: Damage Affecting Performance:

Shredded own spinnaker Forestay tail

Repair: Repair Unsuccessful

Comments

Boat needs some love and a new traveller system. Bilge pump has a hole in the hose Tiller bolt (main bolt) needs tightening - tiller drops. Forestry rail needs replacing Topping lift and pole downhaul need untangling under deck Crack in forestay tail terminating fibreglass base (pre existing) Screw came out of the compass bracket (upper starboard side).