

Camp. Italiano J/70 Equipment Substitution Reques

Received: 2021-10-01 02:00 CEST

Request No: 03 Boat: J 70 - GBR 1452 - Calypso - Marshall King

**Request:** 

**Old Equipment:** Blue AP-1 spinnaker - North Sails.



Blue torn spinnaker (holes 1 & 2).jpg 1.65 MB

**New Equipment:** White AP-1 spinnaker - North Sails - International Class Association registration number 15189.



White Spinnaker.jpg 1.25 MB

## Reason:

We request to replace our Blue North Sails spinnaker due to very significant damage. There are 2 very large holes/tears caused during the racing today (1 October) which make it impossible to sail with the spinnaker without professional repair. The holes are too large to repair with tape, and in positions of high load. We have consulted with the measurer, Egidio Babbi. The North sailmaker, Julio Desiderato, has declared that it is not possible to repair today and so we require a new spinnaker for the remainder of the racing.

## **Response: Approved**

Approved