



## MMNRT II Veloce

### Equipment Substitution Request

Received: 2023-11-04 09:05 CET

---

Request No: 02

Boat: Figaro 3 - Ita 1 - Fenaio - Pendibene Andrea

---

#### Request:

**Old Equipment:**

Code 0 Zaoli

**New Equipment:**


Code 0 north sails

**Reason:**

I opened code0 zaoli after it was taken to the sail loft for repairs. Despite this there are still severe holes and the adhesive does not hold on the sail. I ask to use North sails code because zaoli's code0 is not usable



[IMG\\_1370.jpeg](#) 5.99 MB



[IMG\\_1369.jpeg](#) 5.8 MB



[57191e7b-ea75-4d0c-bae4-260dfc98e50e.jpeg 181 KB](#)



[3f5c17b3-2b49-4a1c-bf46-c1fb9f2e20db.jpeg](#) 175 KB



[9f4e893f-01aa-4c75-88f3-d1117819943b.jpeg](#) 523 KB



[4b4b315f-c0d6-4556-bbfd-bdd083c9dd65.jpeg](#) 167 KB

---

**Response: Approved**

A second Code0 is issues to all boats

---

*Response By Luigi Bertini Printed at 2024-07-01 17:22 CEST*