

Received: 2024-08-09 10:35 CEST

Request No: 10 Boat: International 14 - GBR 1527 - Blue Fire - Philip McDanell Luke Boughton

Request:

Old Equipment: Blue P&B spinnaker

New Equipment:

Blue and yellow Lennon spinnaker

Reason:

Tear in the spinnaker which is around 300mm in length and has a couple of other tears close to this area. It looks like it has been caused by the kite being close to the block and the rope running through the kite causing the tear and wear marks.

Thanks Luke

Response: Approved

Response By Carmelo Paroli Printed at 2024-11-23 05:29 CET