

Received: 2024-08-09 10:35 CEST

Request No: 10

Boat: International 14 - GBR 1527 - Blue Fire - Philip McDanell Luke Boughton

## Request:

## **Old Equipment:**

Blue P&B spinnaker

## **New Equipment:**

Blue and yellow Lennon spinnaker

## Reason:

Tear in the spinnaker which is around 300mm in length and has a couple of other tears close to this area. It looks like it has been caused by the kite being close to the block and the rope running through the kite causing the tear and wear marks.

Thanks Luke

**Response: Approved** 

Response By Carmelo Paroli Printed at 2024-11-23 03:19 CET