



PredictWind 2024 International Moth Class World Championships

Equipment Substitution Request

Received: 2025-01-07 13:31 NZDT

Request No: 21

Boat: Moth - NZL 5121 - Henry Haslett

Request:

Old Equipment:

Mackay Boats MH-V5

New Equipment:

Mackay Boats MH-V5

Reason:

My front horizontal MH-V5 has failed at the flap hinge. The manufacturer Mackay Boats has confirmed the failure and wants to replace the foil with a like for like MH-V5. This failure is unforeseeable and at no fault of my own.

Response: Approved

It will be approved on condition that the broken foil is shown to Allan Punch, Richard Didham, Sam Barnet, Graeme Sutherland for inspection but not one of those from your Country then get Shaun Ritson for the sticker

Response By Harold Bennett Printed at 2025-02-06 06:01 NZDT