

72° Loro Piana Giraglia

Equipment Substitution Request

Received: 2025-06-08 19:25 CEST

Request No: 02 Boat: 3590 - WIND RIDER - CEM ISIL

Request:

Old Equipment:

New Equipment:

Reason:

Racing main sail (carbon) damaged during the race today. There is a ~20 cm hole in the middle and the sail is not fit for use at this condition. We request to continue the regatta with our spare Cruising Sail (white, dacron). We confirm that the spare cruising sail does have ORC measurement and the corresponding ORC sticker on it. Regrettably, the sail does not have our sail number TUR 3590 printed on it. In this context, we respectfully request from the Race Commitee and the OA— (a) permission to use the spare (white, dacron) main sail for the remainder of the regatta. (b) confirm of your approval/permission to use the spare main sail without the sail number. Respectfully, WIND RIDER TUR3590

Response: Approved

Permission granted

Response By Race Office Yacht Club Italiano Printed at 2025-07-18 05:30 CEST