Received: 2025-07-31 11:30 CEST

**Request No: 08** 

**Boat: CONTENDER - GBR 2477 - RABBITING ON - Daniel Hollands** 

# **Request:**

# **Old Equipment:**

Wire shrouds and trapeze lines

### **New Equipment:**

Wire shrouds and dyneema trapeze lines

#### Reason:

Broke a shroud.

Replaced shroud with replacement.

Trapeze line on new shroud is dyneema not wire.

Mast re weighed by Chris Howe, ~150g added lead to achieve correct tip weight. Wire shroudwir

# **Response: Approved**

Mast weight checked, meets requirements for overall weight and tip weight. Substitution accepted.

Response By Chris Howe Printed at 2025-08-02 23:00 CEST