

Maxi Yacht Rolex Cup

Equipment Substitution Request

Received: 2025-09-12 08:20 CEST

Request No: 08

Boat: SM - maxi - Sui 3066 - Inoui - Rodbey Keenan

Request:

Old Equipment:

A4a now destroyed

New Equipment:

Replacing with a1.5 c as attached

Sail list Inoui - 2025

| | | | | | | | | 0.000 |
|--------------|---------|---------------|---------------|-------|-------|--------|--------|---------|
| | A1.5-C | OPA253-004 | | 45.9 | 42.9 | 26.076 | 25.979 | 840.23 |
| | А2-с | OPA253-005 | | 48.1 | 41.95 | 26.155 | 0 | 1041.87 |
| | A2-d | ODK110434-001 | | 48.1 | 41.95 | 26.155 | 0 | 1040.41 |
| | А3-а | 265179 | | 44.8 | 41.4 | 22.496 | 22.495 | 788.44 |
| | A4-a | 265178 | | 46.5 | 41.25 | 25.326 | 0 | 960.06 |
| | Code0-c | OPA184-001 | | 43.15 | 40.7 | 17.849 | 17.1 | 486.13 |
| | Code3-a | OPA144-002 | | 43.85 | 42.2 | 23.94 | 23.579 | 724.58 |
| staysail | GS-a | OPA74-002 | OUS110271-002 | 25.5 | 24.05 | 7.897 | 7.448 | 96.67 |
| | J1-a | 265161 | 99422852-01 | 38.6 | 36.85 | 12.449 | 11.998 | 240.97 |
| | J1-b | ODK110321-001 | | 38.7 | 36.3 | 12.449 | 11.735 | 237.69 |
| | J2-b | ODK102194-002 | OUS110271-001 | 38.7 | 36.7 | 12.449 | 11.847 | 238.14 |
| | J2-c | OPA144-001 | | 38.7 | 36.7 | 12.449 | 11.847 | 237.11 |
| | J2-d | OPA253-003 | | 38.7 | 36.3 | 12.449 | 11.722 | 235.36 |
| | J3-a | 265163 | 99422852-03 | 35.8 | 33.65 | 11.89 | 11.2 | 203.72 |
| Pin-head | MN-4 | OFR17461-002 | | 40.2 | 41.63 | 13.58 | 0 | 340.29 |
| q-top | MN-2 | ODK101967-001 | OUS109643-001 | 40.32 | 41.26 | 13.61 | 0 | 381.34 |
| q-top | MN-3 | OPA253-001 | | 40.32 | 40.68 | 13.58 | 0 | 375.86 |
| ker Staysail | SS-1 | 265181 | | 32.5 | 29.8 | 12.598 | 11.684 | 229.22 |
| il | J-4 | OFR17461-003 | | 30.35 | 28 | 10.549 | 9.758 | 147.08 |

IMG_0854.png 463 KB

Reason:

We have damaged our a4 beyond repair and would like to substitute it for our a1.5 as this is what we have left that is useable

Response: Approved

Response By James Dadd Printed at 2025-11-03 08:30 CET