



## 39 Copa del Rey MAPFRE Question for Officials

**Date:** 2021-08-03

---

**Question No:** 02

**Question For:** Race Committee

**Question:**

Dear Race Committee,

We have tried to sort the issue of the Torqeedo Engine of CS36-1 but unfortunately Torqeedo mechanics, after trying everything and also after having sent their best technician from Germany (the same one that personally installed this engine on this boat years ago), sent us the email below.

<<Hello, The quotation includes a new motor. The problem with the current motor is that the electronic component inside the motor is broken (kindly see picture attached). To replace special tools are needed and for this prototype motor we don't have much spare parts either. If you prefer to try to repair the current motor will have to be sent to us in Germany for the reparation. Will take longer and am not 100% sure if can fix it.

Thank you Mit freundlichen Grüßen | Best regards

**Torqeedo GmbH**Lukas TimckeApplication Engineer

The only solution is to install a new engine and at this point the boat will install a fuel engine like all the others...but there isn't the technical time to make this happen for this event!So we kindly ask you the permission to have rib assistance to exit and enter the port and reach the race course when needed not having a working engine.

Thanks

Thirtysix

---

**Answer:**

Authorized. With the condition you have to be towed in and out the Harbour.  
Sailing is forbidden inside the Harbour.

---