

# Request for Redress

Protest No: 01

Received At: 2021-08-30 22:12 CEST

## 1. Event Name: Marina Militare Nastro Rosa Tour 2021

Protest On: 2021-08-30

Race No: 1

## 2. Hearing Type

- |  |   |
|--|---|
| <input type="checkbox"/> Protest       | <input type="checkbox"/> Request to Reopen              |
| <input type="checkbox"/> Protest by RC | <input type="checkbox"/> Reopening by PC                |
| <input type="checkbox"/> Protest by PC | <input checked="" type="checkbox"/> Request for Redress |
| <input type="checkbox"/> Protest by TC | <input type="checkbox"/> Request for Redress by RC      |

## 3. Protestor

Figaro 3 - Team USA

## 4. Protestees

1. Organizational Authority

## 5. Incident

**Time Place:** During the 1st race

**Rules:**

**Witnesses:**

## 6. Informing Protestee

Hail:

**Hail When:**

**Hail Comment:**

Red Flag:

**Red Flag Comment**

Other:

**Other Comment:** Via email at 14:11

## 7. Description Of Incident

We hope that you would agree that foils are an essential component of a Figaro 3 performance. Similarly we rely on a autopilot for optimal boat handling. Our chartered vessel ITA1 Fenaio experienced a foiling system malfunction during the delivery from France to Italy resulting in port side foil retracting spontaneously by about 2/3. There was also a port side autopilot malfunction which was inoperable. We promptly reported the issues, and a Beneteau representative worked on repairs before the race from Genoa to Civitavecchia. During the race from Genoa and Civitavecchia both the port foil and the port autopilot malfunctioned again: the foil retracted completely, and the autopilot was inoperable. Therefore we respectfully request a redress.

## 8. Damage Or Injury

## Attachments