

# Wayfarer National Championships Equipment Substitution Request

Received: 2023-07-01 18:49 UTC

Request No: 02

Boat: Wayfarer - 11093 - Restless - Andrew Wilson

# Request:

## **Old Equipment:**

Mast

## **New Equipment:**

Mast, borrowed from Tim Wood.

### Reason:

Jib halyard sheeve has failed, preventing jib halyard movement (eg raise or lower jib). No replacement sheeves available at chandlery, so easiest to borrow complete mast.

The masts are similar (one design).

Response: Approved

Response By Paul Jackson Printed at 2024-11-25 01:23 UTC