

## 2023 5O5 World Championship and 2023 No American Championship (Pre-Worlds)

**Equipment Substitution Request** 

## Received: 2023-09-30 07:54 PDT

Request No: 16 Boat: 505 - 8207 - Spot - Ole Eichhirn

**Request:** 

Old Equipment: Superspar M2 mast

New Equipment: Superspar M2 mast

Reason:

Old mast broke while sailing due to corrosion under pole launcher rackets

**Response: Approved** 

new mast approved and completed by TC

Response By Walter Mielke Printed at 2024-07-02 01:42 PDT