

Double Mixed Offshore World Champic Equipment Substitution Request

Received: 2023-10-04 10:58 CEST

Request No: 01

Boat: Dh - 10 - 10 - Karl Book

Request:

Old Equipment:

We still do not have a functional remote control for the autopilot. The organization is working on it now. We cannot dock out

New Equipment:

Reason:

Response: Not Approved

OA fixed. Autopilot including remote was working yesterday during costal race. Today was found with all sources cancelled

Response By Luigi Bertini Printed at 2024-11-24 16:25 CET