



MMNRT II Veloce

Equipment Substitution Request

Received: 2023-11-02 18:54 CET

---

Request No: 01

Boat: Figaro 3 - Ita1 - Fenaio - Andrea Pendibene

---

Request:

**Old Equipment:**

Code 0 zaoli is damage. There is a big delamination for half of the sail. The leech is broken.



[IMG\\_1315.jpeg 3.5 MB](#)



[IMG\\_1321.jpeg 3.64 MB](#)



[IMG\\_1322.jpeg](#) 3.68 MB



[IMG\\_1327.jpeg 2.88 MB](#)



[IMG\\_1318.jpeg 2.74 MB](#)



[IMG\\_1310.jpeg 3 MB](#)



[IMG\\_1309.jpeg 3.63 MB](#)

**New Equipment:**

Code 0. North sail

**Reason:**

I ask to use the code 0 NS because the zaoli's code is damage. Alternatively i ask to have another code0 in good condition and usable for racing

---

**Response: Approved**

A second Code0 is issues to all boats