



J70 World Championship

Equipment Substitution Request

Received: 2024-09-18 18:49 UTC

Request No: 16

Boat: J70 - ESP 1122 - Let it be - Marcelo Baltzer Foucher

Request:

Old Equipment:

harken cam-cleat 150

New Equipment:

harken cam cleat 150

Reason:

The cam cleat of the tack is loose and the tack get loose after holding it to the clam, it is 7 yeras old

Response: Approved

to be finished until 19.09.2024/ 10:00 o'clock

Response By Thomas Loesch Printed at 2024-11-26 01:36 UTC