

## J/70 European Championship 2025

## **Equipment Substitution Request**

Received: 2025-08-27 20:30 CEST

**Request No: 18** 

Boat: European Championship - AUS 1132 - Porco Rosso - Will Sargent

## **Request:**

**Old Equipment:** 

Suzuki 2.5 4 Stroke

**New Equipment:** 

Mercury 5hp 4 stroke

## Reason:

On our charter boat, our Suzuki 2.5 engines drive shaft sheered and is now broken. We have sourced a 5hp mercury to replace this. The Suzuki was 14kg and the Mercury is 25kg. Can we please take 10kg of correctors out of the boat to make up for the difference between these two engines?

**Response: Approved** 

Response By Thomas Loesch Printed at 2025-11-03 15:41 CET