

J105 North American Championship Question for Officials

Date: 2022-09-30

Question No: 01

Question For: Technical Committee

Question:

Our stern pulpit was shoved forward in a collision. We believe the stanchion bases are still secure however the lifelines need to be tied to a new point in order for them to be tightened sufficiently so the crew has secure lifelines. We would like the chief measurer to take into account rule 64.3 so that we are allowed to continue racing.

Answer:

The Technical committee has reviewed Rakusu's repair to their lifelines and determined that they have made all the repairs that can be made in the time available and that it does not confer an advantage. In accordance with RRS 64.4(a), we recommend they be allowed to continue racing.

Response By Paul Zupan Printed at Wed, 03 Jul 2024 11:34:38 +0000