



2021 World Sailing Youth World C Equipment Substitution Request

Received: 2021-12-15 04:00 +04

Request No: 05

Boat: Nacra - Usa - Kay Brunsvold

Request:

Old Equipment:

Tack release grommet pulled out from the tramp

New Equipment:

Requesting a new grommet or other solution in indeed to have a fully functional tack release

Reason:

Manufacturing default

Response: Approved

Repaired

Response By Hendrik Plate Printed at 2024-07-04 09:51 +04