



Kleine Sneekweek

Equipment Substitution Request

Received: 2022-05-27 00:00 CEST

Request No: 03

Boat: Valk - 849 - Siep v.d. Land

Request:

Old Equipment:

zeil 849

New Equipment:

zeil 1194

Reason:

ons grootzeil is defect

Response: Approved

akkoord

Response By Marcel Bult Printed at 2024-05-18 17:35 CEST