

# ILCA Masters Nationals incorporating 2022 EurILCA Master Series

## Equipment Substitution Request

Received: 2022-07-01 01:00 BST

---

**Request No:** 09

**Boat:** ILCA6 - 209933 - MM - Julian Lloyd

---

**Request:**

**Old Equipment:**

Carbon top section

**New Equipment:**

Ali top section

**Reason:**

The bottom collar on my carbon top section has come off. The rivets have ripped out and the collar is stuck in my bottom section. The top section is not useable. I should be able to push the trapped collar down with the replacement ali section - it is not possible to remove trapped collar at the event as it will need tools / drilling etc.

---

**Response: Approved**

---

*Response By Mike Haynes Printed at 2024-07-03 22:01 BST*