

2022 ILCA 6 Youth World Championships

Equipment Substitution Request

Received: 2022-07-28 19:00 CDT

Request No: 16

Boat: ILCA 6 - Silver - 217355 - No name - Thomas Kraak

Request:

Old Equipment:

the center board trunk has a crack in it the is allowing water to come into the boat.

New Equipment:

I'd like to use silicon to close the gap.

Reason:

So that water will not come into my hull and slow me down while I sail

Response: Approved

Repair approved.

Response By Aileen H Loo Printed at 2024-04-30 22:02 CDT