



I14 World Championship

Equipment Substitution Request

Received: 2024-08-07 17:05 CEST

Request No: 04

Boat: CAN 625 - La Dolce Vita - Laventure Lauren Jason Leimieux

Request:

Old Equipment:

T- foil rudder is cracking on the horizontal foils. Unsafe to sail with it and looking to swap for identical rudder.

New Equipment:

Identical t- foil rudder that is undamaged.

Reason:

Cracking on horizontal wings. Unsafe to use.

Response: Approved

Response By Carmelo Paroli Printed at 2024-11-23 05:31 CET