



2025 Formula Kite Europeans

Equipment Substitution Request

Received: 2025-05-18 14:16 +03

Request No: 12

Boat: Male - 36 - Karl Maeder

Request:

Old Equipment:

Rear wing is chipped as shown in the picture



[IMG_3099.jpeg 1.48 MB](#)

serial number 10646908

New Equipment:

The broken rear wing is replaced serial number 10638258

Reason:

Broken rear wing (need to be replace.

Response: Approved

Will be ok once I have serial number of new rear wing
