

J/24 World Championship 2025

□ Equipment Substitution Request

Received: 2025-09-10 18:39 BST

Request No: 02

Boat: J24 - Corinthian - 4241 - Mr. Mann - Shane Hewlett

Request:

Old Equipment:

New Equipment:

Metal plate riveted over the fracture.



[ffb0f37a-1054-4203-92be-7ba03f94d34c.jpeg](#) 156 KB

Reason:

Fracture in boom at vang/kicker connection. Riveted plate put over as repair.

Response: Approved

Thank you for the picture all good ☐

*Response By Michael Peters Printed at 2025-11-03 09:14
GMT*