



## **Eurilca Master European Champions Equipment Substitution Request**

**Received: 2021-07-26 02:00 CEST**

---

**Request No: 02**

**Boat: ILCA 7 - Can 217396 - Ian ELLIOTT**

---

**Request:**

**Old Equipment:**

Boom cracked and bent



[DC7BDD6E-7751-44A9-B719-323F9DCBD958.jpeg 2.03 MB](#)

**New Equipment:**

New boom

**Reason:**

Heavy wind, lots of kicker, boom is about to completely break, it is now unsafe.

---

**Response: Approved**

---

*Response By Jean Bernard Luther Printed at 2024-04-19 23:52 CEST*